Work Order ID 57097 Page 1 Monday, March 22, 2010 8:45:30 AM Item ID: D4018-5 Accept Setup Start **Revision ID:** Stop Item Name: Rib **Start Qty: 24.00 Start Date:** 3/22/2010 **Cust Item ID:** Req'd Qty: 24.00 **Required Date: 3/31/2010 Customer:** Reference: Run Start Process Plan: MF Date: 10-3-22 Tooling: Approvals: Date: Stop QC: SPC (Y/N): Date: Date: Sequence ID/ Operation Set Up/ Draw Draw Plan Reject Accept Reject Work Center ID **Description** Number Rev. Qty Qty **Run Hours** Code Number Stamp Draw Nbr **Revision Nbr** D4018 Α 100 0.00 Large Fab 0.00 Memo Large Fab 1- Cut tube as per dwg D4018 2- debur and remove identification markings 10.03.24 110 QC5- Inspect part completeness to step on W/O 8 10/03/24 0.00 Memo Quality Control Identify as per dwg & Stock Location: Daske 120

0.00

Memo

Packaging

Packaging

W/O:			WC	RK ORDER CHANG	GES		 ·				
DATE	STEP	PRO	OCEDURE CHA	JRE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							· · · · · · · · · · · · · · · · · · ·				
Dord No.											
				_ Fault Category: No							
	Re	esolution:							Date:		
NCR:			WORK ORDI	ER NON-CONFORM	ANCE	(NCR)	1				
DATE	STEP	Description of NC	Corrective Action Section E			Verification			Approval	Approval	
	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector	
					·				!		
									:		
		\- \(\frac{1}{2}\)									
		•									

Work Order ID 57097

Monday, March 22, 2010 8:45:30 AM



Page 2

Item ID:

D4018-5

Accept



Setup Start

Stop



Revision ID:

Start Date:

Rib Item Name:

3/22/2010

Start Qty: 24.00 Req'd Qty: 24.00

Cust Item ID:

Customer:

Reference:

Date:

Tooling:

Date: ____

Start Run

Approvals: QC:

Required Date: 3/31/2010

Process Plan:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/

Operation Work Center ID **Description**

QC21- Final Inspection - Work Order Release

Set Up/ Run Hours Draw Number Draw Rev.

Plan Code

Accept Qty

Reject Reject Qty Number

Stamp

130

Memo

0.00

0.00

Quality Control

Dart	Aeros	pace	Ltd
------	--------------	------	-----

	•									
W/O:			WO	RK ORDER CHANG	GES					
DATE STEP			OCEDURE CHANGE			y	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	ory:	NCR: \	′es N	lo DQ /	A:	_ Date: _	
Resolution:			Disposition: C			QA: N/C Closed: Dat			Date:	
NCR:		,	WORK ORDE	R NON-CONFORM	ANCE (N	ICR)	<u> </u>			
DATE	STEP	Description of NC			ection B		Verification		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		ate	Secti	on C	Chief Eng	QC Inspector
			·							

Picklist Print

Monday, March 22, 2010 8:45:29 AM

Work Order ID: 57097

Parent Item: D4018-5

Parent Item Name:

Comments:

Rib

IPP RevA: new issue DD 09.11.26 verified by:EC

per dwg revA 10.03.15 verified by:EC

IPP Rev:B as

Start Date: 3/22/2010

Required Date: 3/31/2010

Start Qty: 24.00 Required Qty: 24.00

Qty

Component Item ID/ Item Name M304TS0.500W.049

Replacement Mfg/ Item ID

Purch Purchased A PROPERTY AND AND REAL PROPERTY AND A PROPERTY AND

Bin Primary Item Location No

Last Location Unit of

Measure Hand

Qty on Remaining Qty To Pick Issued 253.8035 14.0413

Date Issued

Status

Page 1

Sc

Square Tubing	

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
MAT018	253.8034753	
113303	10.71832	
114004	135.835155	
114161	107.25	

Route


Seq ID

100

P.S. 60.01

	Dart	Aeros	pace	Ltd
--	------	--------------	------	-----

W/O:			WC	RK ORDER CHAN	GES				
DATE	STEP	PR		CEDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:							
	Res	olution:	Disposition	1:	QA: N/C	Closed:		Date: _	
NCR:		·	WORK ORDE	ER NON-CONFORM	IANCE (N	CR)			
DATE	STEP	Description of NC	Corrective Action Section B			Ve	rification	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da		Section C	Chief Eng	QC Inspector
							·		
		•							



Dart Aerospace Ltd	Dart	Aero:	space	Ltd
--------------------	------	-------	-------	-----

W/O:			WC	ORK ORDER CHANG	ES				<u> </u>
DATE	STEP	PRO	OCEDURE CHA	EDURE CHANGE			Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date: _	
		solution:							
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NCF	R)			
DATE	STEP	Description of NC Section A		tion B	Verific	cation	Approval	Approval	
	SIEP		Initial Action Descri Chief Eng Chief Eng		ription Sign &		ion C	Chief Eng	QC Inspector
									,
					 - - - -				
						1			